

FIG. 1




Fig. 1




Fig. 2





Fig. 3

"Profiles" has been selected.



"Ringing
tone" has
been




Fig. 4





Fig. 5


Fig. 6




00042761.0031.01

Ringing tone received.
Soft notification
displayed.


"Option" has
been
pressed.



21 3 22



26 22




24 23 22


"Details"
has been
selected.

"Playback" of the
ringing tone has
been selected.


"Save" has been
pressed in third
display.



24 23 22



27 22




27 22


"OK" has been
pressed or timeout
has expired.

"OTA profile 1"
has been
selected.


"OK" has been
pressed.



24 23 22



27 22



28

Fig. 7

090427030 T9241660